





2009

Construction Safety Findings by category:





2009

Construction Safety Findings by category:





2009

Construction Safety Findings by category:





2009

Construction Safety Findings by category:





2009

Construction Safety Findings by category:





2009

Construction Safety Findings by category:




2009

Construction Safety Findings by category:



2009



Construction Safety Findings by category:



Fall Protection	Electrical	Trenching
PPE	Housekeeping	Ladders
Other		



2009

Construction Safety Findings by category:





2009

Construction Safety Findings by category:





2009

Construction Safety Findings by category:




2009

Construction Safety Findings by category:



2009


Construction Safety Findings by category:



Fall Protection	Electrical	Trenching
PPE	Housekeeping	Ladders
Other		

2009

Construction Safety Findings “OTHER” Safety Findings by category: **22**



2009

Total Construction Safety Findings by month

Total: 48

